



Author	Images
	0
	0
	0
	0
	0
	0
	0
	0
BADGER, RACHEL	1
BADGER, RACHEL   STAIBLE, T F	29
SMITH, PAT G	1
SMITH, PAT G	1

Doc ID	Doc Date	Title
450464	2/22/1996	EPA POTENTIAL HAZARDOUS WASTE SITE - SITE IDENTIFICATION" (THE COPPER SMELTER OPERATED AT THIS SITE FROM APPROXIMATELY 1892 THROUGH 1911; SLAG WASTES WERE DEPOSITED ALONG THE WEST BANKS OF THE ANIMAS RIVER; A BIKE PATH HAS BEEN CONSTRUCTED AND RUNS THROUG
450487	4/3/1996	SITE INVESTIGATION FIELD SAMPLING PLAN DURANGO COPPER SMELTER DURANGO COLORADO
818968	5/3/1996	"EVIDENCE AUDIT CHECKLIST" (RAS NUMBER: 24570, SDG NUMBER: MHBL 36)
818969	6/14/1996	"CSF CHAIN OF CUSTODY FORM" (CASE NUMBER: 24570, SDG NUMBER: MHBL 36; DATA INCLUDED)
818970	4/29/1996	"EVIDENCE AUDIT CHECKLIST" (RAS NUMBER: 24570, SDG NUMBER: HQ 939; FLOPPY DISC INCLUDED)
818971	6/17/1996	"CSF CHAIN OF CUSTODY FORM" (CASE NUMBER: 24570, SDG NUMBER: HQ 939, VOLUME I; DATA INCLUDED)
818972	6/14/1996	"CSF CHAIN OF CUSTODY FORM" (CASE NUMBER: 24570, SDG NUMBER: HQ 939, VOLUME II; DATA INCLUDED)
1054828	3/29/1996	LETTER TRANSMITS THE START SITE INSPECTION OF THE DURANGO COPPER SMELTER
1054829	4/4/1996	SITE INVESTIGATION - FIELD SAMPLING PLAN FOR THE DURANGO COPPER SMELTER
1054830	01/01/1111	LETTER TRANSMITS THE ANALYTICAL RESULTS REPORTS REQUESTED BY THE ADDRESSEE; REPORTS NOT INCLUDED
1054831	01/01/1111	LETTER TRANSMITS THE ANALYTICAL RESULTS REPORT FOR SITE INSPECTION AT THE DURANGO COPPER SMELTER; ARR NOT INCLUDED

Author	Images	Transfer Number	Tracking Number
	0	412070029	402887
	0	412070029	403137
	0	412020219	536383
	0	412020219	536384
	0	412020219	536385
	0	412020219	536386
	0	412020219	536387
BADGER, RACHEL	1		
BADGER, RACHEL   STAIBLE, T F	29		
SMITH, PAT G	1		
SMITH, PAT G	1		